In the case of highly mobile vehicles overloading of the travelling pads (3) of crawler tracks frequently gives rise to incipient cracks in the base plate (14), which generally start from the bottom of the incision of the tongue. A long service life for the travelling pad (3) with base plate (14) is achieved by the base plate (14) being incision-free in the retaining region (10).

(Figure 2)